



Brand:	Volvo	Mileage(km):	233500
Model:	V50	Number of doors:	5
Model type:	1.6 D2 Sport	Vehicle length (cm):	
License plate:	99PZS8	Vehicle width (cm):	
Report code:	4807	Vehicle height (cm):	
Chassis number:	YV1MW84E1B2614807	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	15/04/2011	Power(kw):	84
First NL reg.:	15/04/2011	Transmission	Manual
Color:	Black ☒ Metallic	Number of gears	6
Weight (kg)(kg):	1380	Displacement(cc):	1560
Empty weight(kg):	1280	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Diesel
Top speed (km/h):	195	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.2	EU category:	Euro 5
Cons. outside the city (l/100 km):	3.8	Energy label:	A
Average consumption (l/100 km):	4.3	NL Tax Rate %:	22
Acceleration (s):	11.5	CO2 (g/km):	114
Cargo space (l):	1380	Nb. of Axles:	
Perm. max weight (kg):	1900	APK date:	29/12/2019

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	205/50 R17	Vredestein	7
Tire left rear	All weather	Alloy	205/50 R17	Vredestein	7
Tire right front	All weather	Alloy	205/50 R17	Vredestein	7
Tire right rear	All weather	Alloy	205/50 R17	Vredestein	7

Additional information

No. of keys:	1	☐ Luxury key	☐ Instruction booklet	☒ Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	☒ Odorless
Upholstery:	Half stof/leder			☒ Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	29/12/2018	☒ Display ok
No. of headrests:	5	Last turn mileage(km):	223962	☒ Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Front bumper - Paint repair



Front bumper - Paint repair



Front bumper - Paint repair



Windscreen - Break




bestuurdersstoel beschadigd.

Damages

 Acceptable



Rear left screen - Paint repair



Roof - Restyle deuk(je) en Restyle deuk(jes)

Extra options





