

### Inspected by: Nick van den Heuvel



Brand:	BMW	Mileage(km):	70420
Model:	i3	Number of doors:	5
Model type:	Range Extender	Vehicle length (cm):	
License plate:	4ZDL65	Vehicle width (cm):	
Report code:	3706	Vehicle height (cm):	
Chassis number:	WBY1Z41020VZ73706	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	19/12/2014	Power(kw):	125
First NL reg.:	19/12/2014	Transmission	Automatic
Color:	White Metallic	Number of gears	
Weight (kg)(kg):	1390	Displacement(cc):	647
Empty weight(kg):	1290	Number of cylinders:	2
Wheelbase (cm)(cm):	257	Fuel type:	
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	Euro 6
Cons. outside the city (I/100 km):		Energy label:	Α
Avarage consumption (I/100 km):		NL Tax Rate %:	7
Acceleration (s):	7.9	CO2 (q/km):	13
Cargo space (I):	1390	Nb. of Axles:	
Perm. max weight (kg):	1730	APK date:	19/12/2018

# opties

O.	Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	155/70 R19	Bridgestone	6
Tire left rear	Summer	Alloy	155/70 R19	Bridgestone	6
Tire right front	Summer	Alloy	155/70 R19	Bridgestone	6
Tire right rear	Summer	Alloy	155/70 R19	Bridgestone	6

▲ Additional information	on			
No. of keys:	1 Luxury key	Instruction booklet		Airco works
Interior color:	Grey	Maintenance booklet:	(door dealer, serviceboekje (digitaal))	Odorless
Upholstery:	Stof			Clean inside (Interior is clean)
No. of seats:	4	Stamp date:	09/04/2018	Display ok
No. of headrests:	4	Last turn mileage(km):	63518	Vehicle special usage (None)

# **▲** Cleaning

Clean inside (Interior is clean)

Clean outside

در Damages

Not acceptable







Rear right rim - Scratches



Rear right screen - Paint repair



Front right rim - Scratches

## Damages





Front bumper - Ontzet

## **☎** Extra options



































































AUTOF CTOR