

Inspected by: Nick van den Heuvel



Brand:	BMW	Mileage(km):	40124	
Model:	i3	Number of doors:	5	
Model type:	Basis Comfort Advance 22 kWh	Vehicle length (cm):		
License plate:	GD250Z	Vehicle width (cm):		
Report code:		Vehicle height (cm):		
Chassis number:	WBY1Z21060V306917	Vehicle body type:		
Type of vehicle:	Luxury	Traction:	Rear	
First int. reg.:	06/05/2015	Power(kw):	125	
First NL req.:	06/05/2015	Transmission	Automatic	
Color:	White Metallic	Number of gears		
Weight (kg)(kg):	1270	Displacement(cc):		
Empty weight(kg):	1170	Number of cylinders:		
Wheelbase (cm)(cm):	257	Fuel type:	Electric	
Top speed (km/h):	150	Fuel tank capacity:		
Cons. in the city (I/100 km):		EU category:		
Cons. outside the city (I/100 km):		Energy label:	Α	
Avarage consumption (I/100 km):		NL Tax Rate %:		
Acceleration (s):	7.2	CO2 (q/km):		
Cargo space (I):	1270	Nb. of Axles:		
Perm. max weight (kg):	1620	APK date:	06/05/2019	

opties

oc Tires

Damages

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	155/70 R19	Bridgestone	3
Tire left rear	Summer	Alloy	155/70 R19	Bridgestone	4
Tire right front	Summer	Alloy	155/70 R19	Bridgestone	3
Tire right rear	Summer	Alloy	155/70 R19	Bridgestone	4

A Additional information				
No. of keys:	Luxury key	Instruction booklet		Airco works
Interior color:	Grey	Maintenance booklet:	(door dealer, serviceboekje (digitaal))	Odorless
Upholstery:	Stof			Clean inside (Interior is clean)
No. of seats:	4	Stamp date:	26/04/2017	Display ok
No. of headrests:	4	Last turn mileage(km):	22624	Vehicle special usage (None)

No. of headrests:	4	Last turn mileage(km):	22624	Vehicle special usage (None)
▲ Cleaning				
Clean inside (Interior is clean)				
Clean outside				
Damages				Not acceptable
				Accordable
& Damages				Acceptable



stoelverwarming bestuurderstoel werkt niet

☼ Extra options





























































