



<b>Brand:</b>	BMW	<b>Mileage(km):</b>	143249
<b>Model:</b>	118	<b>Number of doors:</b>	5
<b>Model type:</b>	118d Business	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	36ZRL3	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	8042	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WBA1C11030E868042	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Rear
<b>First int. reg.:</b>	21/01/2013	<b>Power(kw):</b>	105
<b>First NL reg.:</b>	21/01/2013	<b>Transmission</b>	Manual
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1395	<b>Displacement(cc):</b>	1995
<b>Empty weight(kg):</b>	1295	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	269	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	212	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	5.4	<b>EU category:</b>	Euro 5
<b>Cons. outside the city (l/100 km):</b>	3.8	<b>Energy label:</b>	C
<b>Average consumption (l/100 km):</b>	4.4	<b>NL Tax Rate %:</b>	22
<b>Acceleration (s):</b>	8.9	<b>CO2 (g/km):</b>	115
<b>Cargo space (l):</b>	1395	<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>	1850	<b>APK date:</b>	21/01/2020

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R16	Continental	4
Tire left rear	Summer	Alloy	205/55 R16	Continental	4
Tire right front	Summer	Alloy	205/55 R16	Continental	4
Tire right rear	Summer	Alloy	205/55 R16	Continental	4

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	20/09/2017	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	91218	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

## Damages


☒ Not acceptable




Tailgate/ lid - Rust formation

## Damages

Ⓜ Acceptable



Rear right door - Dent



Roof - Dent

## Extra options



