



<b>Brand:</b>	Toyota	<b>Mileage(km):</b>	27498
<b>Model:</b>	Avenis Wagon	<b>Number of doors:</b>	5
<b>Model type:</b>	1.8 Multidrive S Team D*Automaat	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	156113	<b>Vehicle width (cm):</b>	
<b>Report code:</b>		<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	SB1EG76L80E156113	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	28/06/2018	<b>Power(kw):</b>	108
<b>First NL reg.:</b>		<b>Transmission</b>	Automatic
<b>Color:</b>	Silver <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	
<b>Weight (kg)(kg):</b>		<b>Displacement(cc):</b>	1798
<b>Empty weight(kg):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	139
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	215/55 R17		6
Tire left rear	All weather	Alloy	215/55 R17		7
Tire right front	All weather	Alloy	215/55 R17		6
Tire right rear	All weather	Alloy	215/55 R17		7

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>		<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>		<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

Not acceptable



Rear right rim - Scratch



Front left rim - Scratches



Krassen Display

🔧 Damages

🔄 Acceptable

⚙️ Extra options





