



<b>Brand:</b>	Audi	<b>Mileage(km):</b>	283285
<b>Model:</b>	A4 Avant	<b>Number of doors:</b>	5
<b>Model type:</b>	2.0 TDI Pro Line Business	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	61HRG6	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	9926	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WAUZZZ8K49A189926	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	04/02/2009	<b>Power(kw):</b>	105
<b>First NL reg.:</b>	04/02/2009	<b>Transmission</b>	Automatic
<b>Color:</b>	Blue <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	
<b>Weight (kg)(kg):</b>	1630	<b>Displacement(cc):</b>	1968
<b>Empty weight(kg):</b>	1530	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	281	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	200	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	7.5	<b>EU category:</b>	Euro 5
<b>Cons. outside the city (l/100 km):</b>	5	<b>Energy label:</b>	C
<b>Average consumption (l/100 km):</b>	5.9	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	9.7	<b>CO2 (g/km):</b>	155
<b>Cargo space (l):</b>	1630	<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>	2125	<b>APK date:</b>	17/11/2019

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/60 R16	Dunlop	3
Tire left rear	Winter	Alloy	205/60 R16	Dunlop	3
Tire right front	Winter	Alloy	205/60 R16	Dunlop	5
Tire right rear	Winter	Alloy	205/60 R16	Dunlop	6

## Additional information


<b>No. of keys:</b>	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	29/01/2015	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	173365	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

## Damages

⊕ Not acceptable



Windscreen - Pip



Rear bumper - Scratches



Rear right screen - Scratch



Front bumper - Dents



Front bumper - Dent



Front right rim - Scratches

## Damages

⊕ Acceptable



Roof - Paint repair

## Extra options



