

Inspected by: Nick van den Heuvel



		(1)		
Brand:	BMW	Mileage(km):	42414	
Model:	i3	Number of doors:	5	
Model type:	Range Extender Comfort Advance	Vehicle length (cm):		
License plate:	GS896Z	Vehicle width (cm):		
Report code:	6414	Vehicle height (cm):		
Chassis number:	WBY1Z41040VZ76414	Vehicle body type:		
Type of vehicle:	Luxury	Traction:	Rear	
First int. reg.:	14/08/2015	Power(kw):	125	
First NL req.:	14/08/2015	Transmission	Automatic	
Color:	Grey Metallic	Number of gears		
Weight (kg)(kg):	1390	Displacement(cc):	647	
Empty weight(kg):	1290	Number of cylinders:	2	
Wheelbase (cm)(cm):	257	Fuel type:	Hybride (Electro/Benzine) plug-in	
Top speed (km/h):	150	Fuel tank capacity:		
Cons. in the city (I/100 km):		EU category:	Euro 6	
Cons. outside the city (I/100 km):		Energy label:	A	
Avarage consumption (I/100 km):		NL Tax Rate %:	7	
Acceleration (s):	7.9	CO2 (q/km):	13	
Cargo space (I):	1390	Nb. of Axles:		
Perm. max weight (kg):	1730	APK date:	14/08/2019	

♥ opties

🗱 Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	155/70 R19	Bridgestone	5
Tire left rear	Summer	Alloy	155/70 R19	Bridgestone	5
Tire right front	Summer	Alloy	155/70 R19	Bridgestone	5
Tire right rear	Summer	Alloy	155/70 R19	Bridgestone	5

▲ Additional information No. of keys: 2 Luxury key Instruction booklet Airco works Odorless Interior color: Brown Maintenance booklet: (serviceboekje (digitaal)) Upholstery: Leder Clean inside (Interior is clean) No. of seats: Display ok Stamp date: 25/07/2017 No. of headrests: Last turn mileage(km): 29507 Vehicle special usage (None)

A Cleaning

Clean inside (Interior is clean)

Clean outside

Damages

Not acceptable



Rear bumper - Paint repair



Rear bumper - Paint repair



Rear right door - Paint repair



Windscreen - Pip



Front bumper - Paint repair

Damages

🗱 Extra options












































































AUTOFACTOR