



Brand:	Audi	Mileage(km):	305753
Model:	A4 Avant	Number of doors:	5
Model type:	2.0 TDI Pro Line	Vehicle length (cm):	
License plate:	1TFS39	Vehicle width (cm):	
Report code:	9267	Vehicle height (cm):	
Chassis number:	WAUZZZ8K79A199267	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	19/02/2009	Power(kw):	125
First NL reg.:	10/01/2014	Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1595	Displacement(cc):	1968
Empty weight(kg):	1495	Number of cylinders:	4
Wheelbase (cm)(cm):	281	Fuel type:	Diesel
Top speed (km/h):	222	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.2	EU category:	Euro 5
Cons. outside the city (l/100 km):	4.7	Energy label:	B
Average consumption (l/100 km):	5.6	NL Tax Rate %:	
Acceleration (s):	8.6	CO2 (g/km):	149
Cargo space (l):	1595	Nb. of Axles:	
Perm. max weight (kg):	2090	APK date:	31/08/2019

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/50 R17	Vredestein	6
Tire left rear	Winter	Alloy	225/50 R17	Vredestein	4
Tire right front	Winter	Alloy	225/50 R17	Vredestein	6
Tire right rear	Winter	Alloy	225/50 R17	Vredestein	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	11/06/2016	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	212193	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Rear bumper - Scratches



Left tailgate - Break



Rear bumper - Scratches



Front bumper - Paint repair



Front left screen - Paint repair



Koppakking Lek

Damages

⚙ Acceptable



Left sill - Paint repair



Rear left screen - Scratch



Tailgate/ lid - Rust formation

Extra options





