



<b>Brand:</b>	Volvo	<b>Mileage(km):</b>	223728
<b>Model:</b>	V40	<b>Number of doors:</b>	5
<b>Model type:</b>	1.6 D2 Kinetic	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	2SRZ97	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	6420	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	YV1MV8481E2116420	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	30/11/2013	<b>Power(kw):</b>	84
<b>First NL reg.:</b>	30/11/2013	<b>Transmission</b>	Manual
<b>Color:</b>	Black <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1366	<b>Displacement(cc):</b>	1560
<b>Empty weight(kg):</b>	1266	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	265	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	190	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	3.8	<b>EU category:</b>	Euro 5
<b>Cons. outside the city (l/100 km):</b>	3.1	<b>Energy label:</b>	A
<b>Average consumption (l/100 km):</b>	3.4	<b>NL Tax Rate %:</b>	22
<b>Acceleration (s):</b>	11.9	<b>CO2 (g/km):</b>	88
<b>Cargo space (l):</b>	1366	<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>	1890	<b>APK date:</b>	07/09/2019

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R16	Michelin	6
Tire left rear	Winter	Alloy	205/55 R16	Michelin	5
Tire right front	Winter	Alloy	205/55 R16	Michelin	6
Tire right rear	Winter	Alloy	205/55 R16	Michelin	5

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	07/09/2018	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	184105	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

## Damages

☒ Not acceptable



Rear left screen - Scratches



Rear left screen - Scratch



Rear bumper - Paint repair



Rear bumper - Scratches



Rear bumper - Scratches



Tailgate/ lid - Scratches



Rear bumper - Dent



Rear right rim - Scratches



Right sill - Scratches



Front bumper - Scratches



Front bumper - Scratches



Wiellager Lv Hoorbaar

🔑 Damages

⊕ Acceptable

⚙️ Extra options







