



Brand:	BMW	Mileage(km):	355544
Model:	530	Number of doors:	4
Model type:	530d Executive	Vehicle length (cm):	
License plate:	65TPK6	Vehicle width (cm):	
Report code:	7412	Vehicle height (cm):	
Chassis number:	WBAXA51000DW57412	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	16/03/2012	Power(kw):	190
First NL reg.:	16/03/2012	Transmission:	Automatic
Color:	Brown <input checked="" type="checkbox"/> Metallic	Number of gears:	8
Weight (kg)(kg):	1770	Displacement(cc):	2993
Empty weight(kg):	1670	Number of cylinders:	6
Wheelbase (cm)(cm):	297	Fuel type:	Diesel
Top speed (km/h):	250	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.4	EU category:	Euro 5
Cons. outside the city (l/100 km):	4.6	Energy label:	B
Average consumption (l/100 km):	5.3	NL Tax Rate %:	22
Acceleration (s):	6	CO2 (g/km):	139
Cargo space (l):	1770	Nb. of Axles:	
Perm. max weight (kg):	2305	APK date:	16/03/2019

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/55 R17	Dunlop	4
Tire left rear	Summer	Alloy	225/55 R17	Dunlop	6
Tire right front	Summer	Alloy	225/55 R17	Dunlop	4
Tire right rear	Summer	Alloy	225/55 R17	Dunlop	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	29/10/2018	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	345700	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

Damages

☒ Not acceptable



Left outside mirror - Paint repair



Front left door - Paint repair



Rear right rim - Scratches



Front right rim - Scratches



Front bumper - Stone chippings

Damages

⚙ Acceptable



Rear bumper - Dent



Front left door - Paint repair



Front bumper - Dent

Extra options





