



Brand:	Audi	Mileage(km):	166000
Model:	Q7	Number of doors:	5
Model type:	3.0 TDI quattro Clean Diesel Pro Line +	Vehicle length (cm):	
License plate:	1KZK98	Vehicle width (cm):	
Report code:	6671	Vehicle height (cm):	
Chassis number:	WAUZZZ4LXCD026671	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	20/08/2012	Power(kw):	180
First NL req.:	14/08/2013	Transmission	Automatic
Color:	Brown <input checked="" type="checkbox"/> Metallic	Number of gears	8
Weight (kg)(kg):	2345	Displacement(cc):	2967
Empty weight(kg):	2245	Number of cylinders:	6
Wheelbase (cm)(cm):	300	Fuel type:	Diesel
Top speed (km/h):	215	Fuel tank capacity:	
Cons. in the city (l/100 km):	8.6	EU category:	Euro 5
Cons. outside the city (l/100 km):	6.7	Energy label:	C
Average consumption (l/100 km):	7.4	NL Tax Rate %:	22
Acceleration (s):	8.1	CO2 (g/km):	195
Cargo space (l):	2345	Nb. of Axles:	
Perm. max weight (kg):	2995	APK date:	17/04/2019

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	295/35 R21	Vredestein	4
Tire left rear	Summer	Alloy	295/35 R21	Vredestein	4
Tire right front	Summer	Alloy	295/35 R21	Vredestein	4
Tire right rear	Summer	Alloy	295/35 R21	Vredestein	4

Additional information

No. of keys:	3	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Brown	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	15/08/2017	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	146577	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

 Not acceptable



Front left rim - Scratches



Rear bumper - Paint repair



Rear bumper - Scratch



Windscreen - Stone chippings

Damages

 Acceptable



Front left door - Dent



Tailgate/ lid - Paint repair



Front bumper - Paint repair




Bonnet - Scratches






Rear bumper - Break

Extra options



Bose soundsystem







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE