



Brand:	Volvo	Mileage(km):	380040
Model:	V50	Number of doors:	5
Model type:	2.0D Edition II Sport	Vehicle length (cm):	
License plate:	73TRVG	Vehicle width (cm):	
Report code:	6925	Vehicle height (cm):	
Chassis number:	YV1MW755172306925	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	02/01/2007	Power(kw):	100
First NL reg.:	02/01/2007	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1479	Displacement(cc):	1997
Empty weight(kg):	1379	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Diesel
Top speed (km/h):	210	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.6	EU category:	Euro 4
Cons. outside the city (l/100 km):	4.8	Energy label:	C
Average consumption (l/100 km):	5.8	NL Tax Rate %:	
Acceleration (s):	9.6	CO2 (g/km):	154
Cargo space (l):	1479	Nb. of Axles:	
Perm. max weight (kg):	1960	APK date:	06/03/2020

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R16	Goodyear	4
Tire left rear	Winter	Alloy	205/55 R16	Goodyear	3
Tire right front	Winter	Alloy	205/55 R16	Goodyear	4
Tire right rear	Winter	Alloy	205/55 R16	Goodyear	3

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	13/09/2016	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	310339	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Rear left door - Dents



Rear bumper - Dent



Rear right screen - Dents




Front bumper - Paint repair



bestuurdersstoel bekleding gescheurd

Damages

⊗ Acceptable



Roof - Bird droppings

Extra options



