

Inspected by: Nick van den Heuvel



| | | 4 > | |
|------------------------------------|-------------------|----------------------|------------|
| Brand: | BMW | Mileage(km): | 77307 |
| Model: | 518 | Number of doors: | 5 |
| Model type: 518d Executive Aut. | | Vehicle length (cm): | |
| License plate: | GL668R | Vehicle width (cm): | |
| Report code: | 8618 | Vehicle height (cm): | |
| Chassis number: | WBA5L11050D968618 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Rear |
| First int. reg.: | 26/06/2015 | Power(kw): | 110 |
| First NL reg.: | 26/06/2015 | Transmission | Automatic |
| Color: | Grey Metallic | Number of gears | 8 |
| Weight (kg)(kg): | 1805 | Displacement(cc): | 1995 |
| Empty weight(kg): | 1705 | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | 297 | Fuel type: | Diesel |
| Top speed (km/h): | 209 | Fuel tank capacity: | |
| Cons. in the city (I/100 km): | 5.2 | EU category: | Euro 6 |
| Cons. outside the city (I/100 km): | 4.1 | Energy label: | В |
| Avarage consumption (I/100 km): | 4.5 | NL Tax Rate %: | 25 |
| Acceleration (s): | 9.8 | CO2 (q/km): | 118 |
| Cargo space (I): | 1805 | Nb. of Axles: | |
| Perm. max weight (kg): | 2380 | APK date: | 26/06/2019 |

opties

| ₩ _a illes | | | | | |
|----------------------|---------------|----------------|------------|-------------|--------------------------|
| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
| Tire left front | Winter | Allov | 225/55 R17 | Dunlon | 6 |

| position: | type: | type: | | | |
|------------------|--------|-------|------------|--------|---|
| Tire left front | Winter | Alloy | 225/55 R17 | Dunlop | 6 |
| Tire left rear | Winter | Alloy | 225/55 R17 | Dunlop | 5 |
| Tire right front | Winter | Alloy | 225/55 R17 | Dunlop | 6 |
| Tire right rear | Winter | Alloy | 225/55 R17 | Dunlop | 5 |

| ▲ Additional information | | | | | | |
|--------------------------|--------------|------------------------|----------------------------|----------------------------------|--|--|
| No. of keys: | 2 Luxury key | Instruction booklet | | Airco works | | |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (digitaal)) | Odorless | | |
| Upholstery: | Stof | | | Clean inside (Interior is clean) | | |
| No. of seats: | 5 | Stamp date: | 07/02/2019 | Display ok | | |
| No. of headrests: | 5 | Last turn mileage(km): | 63892 | ✓ Vehicle special usage (None) | | |

| | No. of neadrests: | 5 | Last turn mileage(km): | 63892 | Vehicle special usage (None) |
|---|-------------------------------|------|------------------------|-------|------------------------------|
| | | | | | |
| 4 | A Cleaning | | | | |
| | Clean inside (Interior is cle | ean) | | | |
| | Clean outside | | | | |

▶ Damages

® Not acceptable







Rear bumper - Scratch

🗱 Extra options






































































AUTOF CTOR