



| | | | |
|---|---|-----------------------------|------------|
| Brand: | BMW | Mileage(km): | 134644 |
| Model: | 5-serie Gran Turismo | Number of doors: | 5 |
| Model type: | 535xd High Executive | Vehicle length (cm): | |
| License plate: | NB678B | Vehicle width (cm): | |
| Report code: | 0757 | Vehicle height (cm): | |
| Chassis number: | WBAXC41080C990757 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front+Rear |
| First int. reg.: | 18/02/2013 | Power(kw): | 230 |
| First NL reg.: | 22/12/2016 | Transmission | Automatic |
| Color: | Brown <input checked="" type="checkbox"/> Metallic | Number of gears | 8 |
| Weight (kg)(kg): | 2115 | Displacement(cc): | 2993 |
| Empty weight(kg): | 2015 | Number of cylinders: | 6 |
| Wheelbase (cm)(cm): | 307 | Fuel type: | Diesel |
| Top speed (km/h): | 250 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 7.5 | EU category: | Euro 5 |
| Cons. outside the city (l/100 km): | 5.7 | Energy label: | C |
| Average consumption (l/100 km): | 6.4 | NL Tax Rate %: | 22 |
| Acceleration (s): | 5.6 | CO2 (g/km): | 168 |
| Cargo space (l): | 2115 | Nb. of Axles: | |
| Perm. max weight (kg): | 2660 | APK date: | 27/12/2019 |

opties

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Winter | Alloy | 245/45 R19 | Dunlop | 6 |
| Tire left rear | Winter | Alloy | 245/45 R19 | Dunlop | 6 |
| Tire right front | Winter | Alloy | 245/45 R19 | Dunlop | 6 |
| Tire right rear | Winter | Alloy | 245/45 R19 | Dunlop | 6 |

Additional information

| | | | | |
|--------------------------|-------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Beige | Maintenance booklet: | (serviceboekje (digitaal)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 02/08/2017 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 110207 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

Damages

☒ Not acceptable



Rear left rim - Scratches



Rear right rim - Scratches



Front right rim - Scratches



Front bumper - Scratches



airco knop achterin ontbreekt

🔧 Damages

⊗ Acceptable

⚙ Extra options





