



<b>Brand:</b>	Audi	<b>Mileage(km):</b>	206269
<b>Model:</b>	A6 Avant	<b>Number of doors:</b>	5
<b>Model type:</b>	2.0 TFSI Advance Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	42SGL5	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	2286	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WAUZZZ4F0BN032286	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	27/09/2011	<b>Power(kw):</b>	125
<b>First NL reg.:</b>	27/09/2011	<b>Transmission</b>	Automatic
<b>Color:</b>	Black <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	
<b>Weight (kg)(kg):</b>	1710	<b>Displacement(cc):</b>	1984
<b>Empty weight(kg):</b>	1610	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	284	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	220	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	10.5	<b>EU category:</b>	Euro 5
<b>Cons. outside the city (l/100 km):</b>	6.2	<b>Energy label:</b>	B
<b>Average consumption (l/100 km):</b>	7.8	<b>NL Tax Rate %:</b>	22
<b>Acceleration (s):</b>	8.8	<b>CO2 (g/km):</b>	181
<b>Cargo space (l):</b>	1710	<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>	2265	<b>APK date:</b>	09/04/2020

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/45 R17	Continental	6
Tire left rear	Summer	Alloy	225/45 R17	Continental	6
Tire right front	Summer	Alloy	225/45 R17	Continental	6
Tire right rear	Summer	Alloy	225/45 R17	Continental	6

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>		<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	94591	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

## Damages

☒ Not acceptable



Front bumper - Paint repair

## Damages

 Acceptable



Rear left door - Paint repair



Tailgate/ lid - Paint repair



Left tailgate - Weatherworn



Right tailgate - Weatherworn



Front right rim - Scratch



Windscreen - Stone chippings



Front bumper - Paint repair



Front bumper - Scratch

## Extra options







