



<b>Brand:</b>	Audi	<b>Mileage(km):</b>	88531
<b>Model:</b>	A3 Sportback	<b>Number of doors:</b>	5
<b>Model type:</b>	1.4 TFSI Attraction S-Line Exterieur	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	ZD109D	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	6766	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WAUZZZ8V4GA096766	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	28/01/2016	<b>Power(kw):</b>	92
<b>First NL req.:</b>	29/04/2019	<b>Transmission:</b>	Manual
<b>Color:</b>	White <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	
<b>Weight (kg)(kg):</b>	1205	<b>Displacement(cc):</b>	1395
<b>Empty weight(kg):</b>	1105	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	264	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	206	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	C
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	117
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	28/01/2020

### ⚙️ opties

### ⚙️ Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/45 R17	Continental	5
Tire left rear	Winter	Alloy	225/45 R17	Continental	7
Tire right front	Winter	Alloy	225/45 R17	Continental	5
Tire right rear	Winter	Alloy	225/45 R17	Continental	7

### ⚠️ Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	02/12/2016	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	30239	<input checked="" type="checkbox"/> Vehicle special usage (None)

### ⚠️ Cleaning

- Clean inside (Interior is clean)
- Clean outside

### 🔧 Damages

⊕ Not acceptable




Front left rim - Scratch



Rear bumper - Paint repair



Front bumper - Paint repair



Bonnet - Dent



Front right rim - Scratch



Roof - Dent



Roof - Paint repair



Roof - Paint repair

 Damages

 Acceptable

 Extra options



