

Inspected by: Nick van den Heuvel



Brand:	D1 014	Miles and (laws).	1 40000
Brand:	BMW	Mileage(km):	142302
Model:	X1	Number of doors:	5
Model type:	2.0d sDrive High Executive Aut.	Vehicle length (cm):	
License plate:	5ZNS97	Vehicle width (cm):	
Report code:	2062	Vehicle height (cm):	
Chassis number:	WBAVP91060VV42062	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	31/01/2014	Power(kw):	135
First NL req.:	09/02/2015	Transmission	Automatic
Color:	Grey Metallic	Number of gears	8
Weight (kg)(kg):	1660	Displacement(cc):	1995
Empty weight(kg):	1560	Number of cylinders:	4
Wheelbase (cm)(cm):	276	Fuel type:	Diesel
Top speed (km/h):	218	Fuel tank capacity:	
Cons. in the city (I/100 km):	6.1	EU category:	Euro 5
Cons. outside the city (I/100 km):	5.1	Energy label:	F
Avarage consumption (I/100 km):	5.4	NL Tax Rate %:	22
Acceleration (s):	7.7	CO2 (q/km):	143
Cargo space (I):	1660	Nb. of Axles:	
Perm. max weight (kg):	2145	APK date:	31/01/2020

♥ opties

🗱 Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	225/50 R17	Pirelli	5
Tire left rear	Summer	Alloy	225/50 R17	Pirelli	5
Tire right front	Summer	Alloy	225/50 R17	Pirelli	5
Tire right rear	Summer	Alloy	225/50 R17	Pirelli	5

▲ Additional informatio	n			
No. of keys:	2 Luxury key	Instruction booklet		Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	19/01/2017	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	74251	▼ Vehicle special usage (None)

▲ Cleaning

Clean inside (Interior is clean)

Clean outside (Polishing)

Damages

Not acceptable



Rear bumper - Paint repair

Damages










Rear right door - Scratch

Front bumper - Dent

Bonnet - Dent



Rear left screen - Dent

♥ Extra options























