



Brand:	Hyundai	Mileage(km):	22669
Model:	iX20	Number of doors:	5
Model type:	1.6 CVVT 125pk Go! Aut.	Vehicle length (cm):	
License plate:	267556	Vehicle width (cm):	
Report code:	7556	Vehicle height (cm):	
Chassis number:	TMAPT81DBJJ267556	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	12/08/2017	Power(kw):	92
First NL reg.:		Transmission	Automatic
Color:	White <input type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1591
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	150
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Steel	195/65 R15	Continental	6
Tire left rear	Summer	Steel	195/65 R15	Continental	5
Tire right front	Summer	Steel	195/65 R15	Continental	6
Tire right rear	Summer	Steel	195/65 R15	Continental	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	02/09/2020	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	22271	<input checked="" type="checkbox"/> Vehicle special usage (None)


Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

Damages

☒ Not acceptable



Rear bumper - Paint repair

🔧 Damages

🟢 Acceptable

⚙️ Extra options

