

Inspected by: Mike Otten

Acceptable



Brand:	Fiat	Mileage(km):	71697
Model:	Tipo	Number of doors:	5
Model type:	1.6 MultiJet 16v Business Lusso	Vehicle length (cm):	
License plate:	TB352R	Vehicle width (cm):	
Report code:	8833	Vehicle height (cm):	
Chassis number:	ZFA35600006J88833	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	29/06/2018	Power(kw):	88
First NL req.:	29/06/2018	Transmission	Manual
Color:	Blue Metallic	Number of gears	
Weight (kg)(kg):	1395	Displacement(cc):	1598
Empty weight(kg):	1295	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Diesel
Top speed (km/h):	200	Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	Euro 6
Cons. outside the city (I/100 km):		Energy label:	С
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	89
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	29/06/2021

opties

o: Tires

Damages

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	205/55 R16	Hankook	4
Tire left rear	Summer	Alloy	205/55 R16	Goodyear	5
Tire right front	Summer	Alloy	205/55 R16	Hankook	4
Tire right rear	Summer	Alloy	205/55 R16	Goodyear	5

▲ Additional information	on			
No. of keys:	2 Luxury key	Instruction booklet		Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	22/07/2019	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	35663	Vehicle special usage (None)


No. of headrests:	5	Last turn mileage(km):	35663	▼ Vehicle special usage (None)
Cleaning				
Clean inside (Interior	is clean)			
Clean outside (Polish	ing)			
Damages				Not acceptable







Roof - Scratch



Roof - Restyle dent



Windscreen - Pip

¢^a Extra options







