



<b>Brand:</b>	Citroen	<b>Mileage(km):</b>	56342
<b>Model:</b>	C4 Picasso	<b>Number of doors:</b>	5
<b>Model type:</b>	1.6 THP 165pk Intensive Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	830892	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	0892	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF73D5GZTFJ830892	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	14/12/2015	<b>Power(kw):</b>	121
<b>First NL req.:</b>		<b>Transmission</b>	Automatic
<b>Color:</b>	White <input type="checkbox"/> Metallic	<b>Number of gears</b>	
<b>Weight (kg)(kg):</b>		<b>Displacement(cc):</b>	1600
<b>Empty weight(kg):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	131
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/60 R16	Michelin	5
Tire left rear	Summer	Alloy	205/60 R16	Michelin	5
Tire right front	Summer	Alloy	205/60 R16	Michelin	5
Tire right rear	Summer	Alloy	205/60 R16	Michelin	5

## Additional information

<b>No. of keys:</b>	2 <input type="checkbox"/> Luxury key <input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Miscellaneous <a href="#">Maintenance booklet:</a> (serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof	<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5 <a href="#">Stamp date:</a> 26/11/2019	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5 <a href="#">Last turn mileage(km):</a> 48000	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

Not acceptable



Rear left rim - Scratch

🔑 Damages

🟢 Acceptable

⚙️ Extra options



