

#### Inspected by: Mike Otten




Brand:	BMW	Mileage(km):	99658
Model:	3-serie	Number of doors:	2
Model type:	320i M-Sport Aut.	Vehicle length (cm):	
License plate:	77TLR4	Vehicle width (cm):	
Report code:	5365	Vehicle height (cm):	
Chassis number:	WBADV51060E425365	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	02/03/2012	Power(kw):	125
First NL reg.:	02/03/2012	Transmission	Automatic
Color:	Blue 🔽 Metallic	Number of gears	6
Weight (kg)(kg):	1700	Displacement(cc):	1995
Empty weight(kg):	1600	Number of cylinders:	4
Wheelbase (cm)(cm):	276	Fuel type:	Petrol
Top speed (km/h):	226	Fuel tank capacity:	
Cons. in the city (l/100 km):	9.8	EU category:	Euro 5
Cons. outside the city (I/100 km):	5.8	Energy label:	D
Avarage consumption (I/100 km):	7.3	NL Tax Rate %:	
Acceleration (s):	9.8	CO2 (a/km):	169
Cargo space (I):	1700	Nb. of Axles:	2
Perm. max weight (kg):	2055	APK date:	29/12/2020

# 📽 opties

¢₀ Tires						
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):	
Tire left front	Summer	Alloy	225/35 R19	Bridgestone	7	
Tire left rear	Summer	Alloy	255/30 R19	Bridgestone	3	
Tire right from	nt Summer	Alloy	225/35 R19	Bridgestone	7	
Tire right rea	r Summer	Alloy	255/30 R19	Bridgestone	3	

Additional informati	on			
No. of keys:	2 🗌 Luxury key	Instruction booklet		Airco works
Interior color:	Beige	Maintenance booklet:	(serviceboekje (papier))	Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	4	Stamp date:	22/05/2019	Display ok
No. of headrests:	4	Last turn mileage(km):	92624	Vehicle special usage (None)

▲ Cleaning	
Clean inside (Interior is clean)	
Clean outside	
۶ Damages	Not acceptable







Right outside mirror - Paint repair


Acceptable

## 🖋 Damages



Roof - Restyle dent

### **\$** Extra options



































































### AUTOFACTOR SOFTWARE FOR AUTOMOTIVE