



<b>Brand:</b>	BMW	<b>Mileage(km):</b>	33485
<b>Model:</b>	3-serie	<b>Number of doors:</b>	5
<b>Model type:</b>	Touring 320xd 190pk Advantage Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	H612HX	<b>Vehicle width (cm):</b>	
<b>Report code:</b>		<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WBA8J11000K849700	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front+Rear
<b>First int. reg.:</b>	23/07/2018	<b>Power(kw):</b>	140
<b>First NL req.:</b>	06/02/2020	<b>Transmission</b>	Automatic
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	8
<b>Weight (kg)(kg):</b>	1760	<b>Displacement(cc):</b>	1995
<b>Empty weight(kg):</b>	1660	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	281	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	226	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	F
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	7.5	<b>CO2 (g/km):</b>	124
<b>Cargo space (l):</b>	1760	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	2180	<b>APK date:</b>	23/07/2021

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/45 R18	Pirelli	6
Tire left rear	Summer	Alloy	225/45 R18	Pirelli	6
Tire right front	Summer	Alloy	225/45 R18	Pirelli	6
Tire right rear	Summer	Alloy	225/45 R18	Pirelli	6

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	18/11/2019	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	19261	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning


- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

Not acceptable



Rear bumper - Scratch



Rear bumper - Scratch



Front right rim - Scratch



Front right rim - Scratch



Rear right screen - Dent



Rear right rim - Scratch



Rear right rim - Scratch

## Damages


⊗ Acceptable




Front left screen - Restyle dent

## Extra options











AUTOF<sup>▲</sup>CTOR  
SOFTWARE FOR AUTOMOTIVE