

Inspected by: Mike Otten



Brand:	Citroen	Mileage(km):	22020
Model:	C3 Aircross	Number of doors:	5
Model type:	1.2 PureTech 110pk Shine	Vehicle length (cm):	
License plate:	471246	Vehicle width (cm):	
Report code:	1246	Vehicle height (cm):	
Chassis number:	VF72RHNPMK4471246	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	18/02/2020	Power(kw):	81
First NL req.:		Transmission	Manual
Color:	White Metallic	Number of gears	
Weight (kg)(kg):	_	Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	3
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

¢^a opties

o: Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather		205/60 R16	Hankook	6
Tire left rear	All weather		205/60 R16	Hankook	7
Tire right front	All weather		205/60 R16	Hankook	6
Tire right rear	All weather		205/60 R16	Hankook	7

▲ Additional information	n			
No. of keys:	2 Luxury key	Instruction booklet		✓ Airco works
Interior color:	Miscellaneous	Maintenance booklet:	(serviceboekje (papier))	Odorless
Upholstery:	Stof			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		✓ Display ok
No. of headrests:	5	Last turn mileage(km):		✓ Vehicle special usage (None)

No. of seats:	5	Stamp date:	☑ Display ok
No. of headrests:	5	Last turn mileage(km):	▼ Vehicle special usage (None)
▲ Cleaning			
Clean inside (Interior	is clean)		
Clean outside			
▶ Damages			Not acceptable
✗ Damages			Acceptable







Rear right door - Restyle dent

c^a Extra options
































































AUTOF CTOR