

Inspected by: Mike Otten



Brand:	Mazda	Mileage(km):	31597
Model:	CX-3	Number of doors:	5
Model type:	2.0 SkyActiv-G 121pk	Vehicle length (cm):	•
License plate:	TS+ Aut. 407213	Vehicle width (cm):	
Report code:	7213	Vehicle height (cm):	
Chassis number:	JMZDK6W7A01407213	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	28/09/2018	Power(kw):	89
First NL req.:		Transmission	Automatic
Color:	Grey Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	2000
Empty weight(kg):		Number of cylinders:	4
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

oc Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	215/60 R16	Bridgestone	4
Tire left rear	Summer	Alloy	215/60 R16	Bridgestone	6
Tire right front	Summer	Alloy	215/60 R16	Bridgestone	4
Tire right rear	Summer	Alloy	215/60 R16	Bridgestone	6

Additional information	า			
No. of keys:	2 Luxury key	Instruction booklet		✓ Airco works
Interior color:	Black	Maintenance booklet:	(door dealer)	Odorless
Upholstery:	Stof			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		✓ Display ok
No. of headrests:	5	Last turn mileage(km):		✓ Vehicle special usage (None)

▲ Cleaning

Clean inside (Interior is clean)

Clean outside


Damages

Not acceptable



Navigatie knop blijft wat dieper liggen


Damages





Roof - Restyle dent

Acceptable



Roof - Restyle dent

¢^a Extra options



























































