

Inspected by: Mike Otten



Brand:	Suzuki	Mileage(km):	188046
Model:	Vitara	Number of doors:	5
Model type:	1.6D High Executive	Vehicle length (cm):	
License plate:	SK987Z	Vehicle width (cm):	
Report code:	3983	Vehicle height (cm):	
Chassis number:	TSMLYD81S00473983	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	26/04/2018	Power(kw):	88
First NL reg.:	26/04/2018	Transmission	Manual
Color:	Orange Metallic	Number of gears	6
Weight (kg)(kg):	1305	Displacement(cc):	1598
Empty weight(kg):	1205	Number of cylinders:	4
Wheelbase (cm)(cm):	250	Fuel type:	Diesel
Top speed (km/h):	180	Fuel tank capacity:	
Cons. in the city (I/100 km):	4.6	EU category:	Euro 6
Cons. outside the city (I/100 km):	3.7	Energy label:	E
Avarage consumption (I/100 km):	4	NL Tax Rate %:	
Acceleration (s):	11.5	CO2 (q/km):	106
Cargo space (I):	1305	Nb. of Axles:	2
Perm. max weight (kg):	1870	APK date:	26/04/2021

o^a opties

oc Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/55 R17	Continental	3
Tire left rear	Summer	Alloy	215/55 R17	Continental	5
Tire right front	Summer	Alloy	215/55 R17	Continental	3
Tire right rear	Summer	Alloy	215/55 R17	Continental	5

▲ Additional informatio	n			
No. of keys:	2 Luxury key	Instruction booklet		✓ Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
Upholstery:	Half stof/leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	15/07/2020	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	158649	✓ Vehicle special usage (Learning car)

▲ Cleaning

Clean inside (Interior is clean)

Clean outside

در Damages

Not acceptable



Bonnet - Stone chippings



Roof - Hail damage



Roof - Hail damage

Acceptable

Damages



Rear right door - Restyle dent



Bonnet - Restyle dent



Bonnet - Restyle dent

¢^a Extra options




































































AUTOF CTOR