



| | | | |
|---|--|-----------------------------|---------------------------------------|
| Brand: | Hyundai | Mileage(km): | 3099 |
| Model: | Kona | Number of doors: | 5 |
| Model type: | 1.6 GDI HEV Premium | Vehicle length (cm): | |
| License plate: | 029849 | Vehicle width (cm): | |
| Report code: | 9849 | Vehicle height (cm): | |
| Chassis number: | KMHK581EGLU029849 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 17/06/2020 | Power(kw): | 77 |
| First NL reg.: | | Transmission | Automatic |
| Color: | Blue <input checked="" type="checkbox"/> Metallic | Number of gears | |
| Weight (kg)(kg): | | Displacement(cc): | 1600 |
| Empty weight(kg): | | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | | Fuel type: | Hybride (Electro/Benzine) non plug-in |
| Top speed (km/h): | | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | | EU category: | |
| Cons. outside the city (l/100 km): | | Energy label: | |
| Average consumption (l/100 km): | | NL Tax Rate %: | |
| Acceleration (s): | | CO2 (g/km): | |
| Cargo space (l): | | Nb. of Axles: | 2 |
| Perm. max weight (kg): | | APK date: | |

opties

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Summer | Alloy | 225/45 R18 | Michelin | 6 |
| Tire left rear | Summer | Alloy | 225/45 R18 | Michelin | 7 |
| Tire right front | Summer | Alloy | 225/45 R18 | Michelin | 6 |
| Tire right rear | Summer | Alloy | 225/45 R18 | Michelin | 7 |

Additional information

| | | | | |
|--------------------------|-------|-------------------------------------|---|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input checked="" type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 14/06/2021 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 2687 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

⊗ Not acceptable

Damages

⊗ Acceptable

Extra options



Stoelverwarming achterin




krell



draadloos opladen







AUTOFACTOR
SOFTWARE FOR AUTOMOTIVE