

Inspected by: Marco Oosten



Brand:	Audi	Mileage(km):	219357
Model:	Q5	Number of doors:	5
Model type:	3.0 TDI quattro Pro Line Aut.	Vehicle length (cm):	
License plate:	08TRD1	Vehicle width (cm):	
Report code:	0207	Vehicle height (cm):	
Chassis number:	WAUZZZ8R8CA090207	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	26/03/2012	Power(kw):	176
First NL req.:	26/03/2012	Transmission	Automatic
Color:	Black Metallic	Number of gears	7
Weight (kg)(kg):			2967
Empty weight(kg):	1855	Number of cylinders:	6
Wheelbase (cm)(cm):	281	Fuel type:	Diesel
Top speed (km/h):	225	Fuel tank capacity:	
Cons. in the city (I/100 km):	9.2	EU category:	Euro 5
Cons. outside the city (I/100 km):	6.6	Energy label:	F
Avarage consumption (I/100 km):	7.5	NL Tax Rate %:	
Acceleration (s):	6.5	CO2 (q/km):	199
Cargo space (I):	1955	Nb. of Axles:	2
Perm. max weight (kg):	2490	APK date:	08/02/2021

opties

Leather upholstery

Air suspension

Bang & Olufsen Power steering

Remote central locking

4x4 performance

Licht Sensor

Alloy wheels

Front seats adjustable in height

SOSSSSSSSSSSSSSS ABS

Multifunctional steering wheel

Fog lamps

Roof rail (silver)

Metallic finish Bi-xenon headlights Headlight washers
LED rear lights
Exterior mirrors in co

Exterior mirrors in car body color

Rear wiper $[\checkmark]$

Rear parking sensors

Front parking sensors

>>> Rear-seat folding (unequal parts)

Luggage cover

Spare wheel (full)

Aux connection

Bluetooth streaming

Radio/CD player

Bluetooth car kit Cruise control

Airconditioning in the back

Head-up Display
Airconditioning in
Climate control (c
Climate control (l
Heater Climate control (digital)

Climate control (L/R separated)

Large screen navigation

Electrically operated rear windows

Large screen navigation

Electrically operated review Electrically folding mirror

Central armrest front

Audio control on the ste

Leather steering wheel

Airbag(s) front + flank Electrically operated front windows

Electrically folding mirrors

Audio control on the steering wheel

🗱 Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	235/65 R17	Vredestein	6
Tire left rear	All weather	Alloy	235/65 R17	Vredestein	6
Tire right front	All weather	Alloy	235/65 R17	Vredestein	6
Tire right rear	All weather	Alloy	235/65 R17	Vredestein	6

Additional information

	No. of keys:	2 Luxury key	☐ Instruction booklet		Airco works
	Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless (Nee. ruikt naar rook)
	Upholstery:	Leder			Clean inside (Interior is clean)
	No. of seats:	5	Stamp date:	22/01/2020	✓ Display ok
	No. of headrests:	5	Last turn mileage(km):	194224	✓ Vehicle special usage (None)

A Cleaning

Clean inside (Interior is clean)

Clean outside (Polishing)

Damages

Not acceptable

Acceptable







Front bumper - Paint repair




Front bumper - Paint repair


Damages



Front left screen - Scratch



Bonnet - Restyle dent



Roof - Restyle dent

¢[‡] Extra options





























































